Minebea Co., Ltd.

List of reference numbers

10-1, 10-2, 10-3, 10-4, 10-5, 10-6	laminations
12	slots
14	inner opening
16	outer periphery
18	bridges
20	shallow slots or notches
22	centerline
30-1, 30-2, 30-3	stator sheets
32	stator yoke
34	stator poles or teeth
36	shallow slots or notches
38	stator assembly
40	grooves
42	poles
50	embedded magnets
110	shaft
112	yoke
114	housing
116	rotor assembly
118	stator assembly
122	permanent magnets
124	flange
126, 128	bearings
155	sheet metals
160	windings